

FS&EB ACTION CONTROL FORM

A. Action Code CDR#159
Name of Licensee and Facility Metropolitan Edison Co. (Three Mile Island)
Docket No. or License No. 50-289
Title Grease Leakage from Reactor Building Tendons
Origin Licensee Date Rec'd 8/28/73

B. FS&EB Branch Coordinator:

Bryan _____ Dreher X
Ellis _____ Paulus _____
Completion Requested by _____

C. Action Requested of:

ADREMP _____ M&PPOB _____ EPB _____ RPB _____ ADCO _____
OE _____ CB _____ TAB _____ OOE _____ Region I
Date Requested 8/30/73 Completion Requested by _____
Reference CDR dated 8/17/73 from Metropolitan Edison Company


D. Action Requested

In accordance with PI 0600/6 "Construction Deficiency Reporting," the Metropolitan Edison Company, report of 8/17/73, covering the Grease Leakage from Reactor Building Tendons, is being assigned to Region I for evaluation of technical adequacy of the corrective action being taken and final resolution of the deficiency.

E. Date Action Completed _____

Close-out (Date & Method) _____

Comments: If completion date is not consistent with your work schedule, please let us know.


J. G. Davis, Deputy Director
for Field Operations
Directorate of Regulatory Operations

1557 346

7911070653

7/10/76