

APPENDIX A

Bomhoff and Associates, Inc.
Anchorage Alaska

License No. 50-18034-01

NOTICE OF VIOLATION

Based upon the results of the NRC inspection conducted on September 14, 1979, certain activities under your license appear to be in noncompliance with NRC requirements as indicated below:

1. Contrary to License Condition 12, licensed materials were used in 1979 by personnel not in the physical presence of the authorized user.

This is an infraction.

2. Contrary to License Condition 14(a)(1), which requires leak tests of the sealed source at six month intervals, the licensed sealed source had not been leak tested between August, 1978 and September, 1979.

This is an infraction.

3. License Condition 16 requires the licensee to possess and use licensed material in accordance with statements, representations, and procedures contained in the application dated February 23, 1978. Item 12 of that application stated that film badges would be used.

Contrary to the above, personnel monitoring film badges were not available from June, 1978 to June, 1979 during the use of the licensed materials.

This is an infraction.

4. Contrary to 10 CFR 30.51, receipt record of the licensed material was not maintained.

This is a deficiency.

2117 009