

REGULATORY FILE COPY

DISTRIBUTION

Central Files

P&TRB Reading

NRR Reading

J. Kramer

S. Hanauer

D. Ziemann

D. Beckham

NOV 05 1980

NOV 7 1980  
DIVISION OF SAFETY SERVICES  
BRANCH

NOV 7 1980

MEMORANDUM FOR: Frank Schroeder, Acting Director  
Division of Safety Technology

FROM: Stephen H. Hanauer, Director  
Division of Human Factors Safety

SUBJECT: SAFETY INJECTION SIGNAL RESET

Your September 30, 1980 memorandum forwarded a review of the potential problem created when resetting safety injection at the Point Beach plant could negate the automatic actuation of other safety functions. You recommended that we consider this in our reviews of plant-specific procedures under Task Action Plan Items I.C.8 and I.C.9. The reviewers in the Procedures and Test Review Branch have been reviewing the consequences of resetting safety injection in the plant reviews conducted to date and have required specific action steps, where necessary, to ensure proper safety function actuation. We will continue to include this in our reviews conducted under Item I.C.8 and will consider it in developing the long-term program called for in Item I.C.9.

Original signed by

*Stephen H. Hanauer*  
Stephen H. Hanauer, Director  
Division of Human Factors Safety

cc: D. Eisenhut  
D. Ross  
P. Check  
T. Speis  
R. Vollmer  
A. Thadani  
R. Bernero  
F. Rowsom  
R. Baer  
T. Cox  
S. Israel  
J. T. Beard

|         |              |            |           |  |  |
|---------|--------------|------------|-----------|--|--|
| OFFICE  | DHFS:P&TRB   | DHFS:P&TRB | DHFS:DR   |  |  |
| SURNAME | DHBeckham:ah | DLZiemann  | SHHanauer |  |  |
| DATE    | 11/3/80      | 11/4/80    | 11/5/80   |  |  |

8011180368

P