



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION II
101 MARIETTA ST., N.W., SUITE 3100
ATLANTA, GEORGIA 30303

TIC

NOV 7 1980

In Reply Refer To:
RII:GLT
50-364/80-44

Alabama Power Company
ATTN: R. P. McDonald
Vice President-Nuclear Generation
P. O. Box 2641
Birmingham, AL 35291

Gentlemen:

This refers to the inspection conducted by G. L. Troup of this office on October 14-17, 1980, of activities authorized by NRC Construction Permit No. CPPR-86 for the Farley facility, and to the discussion of our findings held with W. G. Hairston, III at the conclusion of the inspection.

Areas examined during the inspection and our findings are discussed in the enclosed inspection report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector.

Within the scope of this inspection, no items of noncompliance were disclosed.

In accordance with Section 2.790 of the NRC's "Rules of Practice", Part 2, Title 10, Code of Federal Regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC's Public Document Room. If this report contains any information that you (or your contractor) believe to be proprietary, it is necessary that you make a written application within 20 days to this office to withhold such information from public disclosure. Any such application must include a full statement of the reasons on the basis of which it is claimed that the information is proprietary, and should be prepared so that proprietary information identified in the application is contained in a separate part of the document. If we do not hear from you in this regard within the specified period, the report will be placed in the Public Document Room.

Should you have any questions concerning this letter, we will be glad to discuss them with you.

REGISTRATION
SERVICES UNIT
1980 DEC 12 4 10 2
U.S. NRC
POSTAL
COMMUNICATIONS
SERVICES
BRANCH

Sincerely,

J. Philip Stohr, Chief
Fuel Facility and Materials
Safety Branch

for

Enclosure: (See Page 2)

8012130 214

Enclosure:

Inspection Report No. 50-364/80-44

cc w/encl:

W. O. Whitt, Executive Vice President
H. O. Thrash, Manager, Nuclear Generation
F. L. Clayton, Jr., Senior Vice President
W. C. Petty, Manager-Quality Assurance
(Design and Construction)
W. G. Hairston, III, Plant Manager
R. E. Hollands, Jr., QA Supervisor
O. D. Kingsley, Jr., Manager, Nuclear Engineering
and Technical Services