



Carolina Power & Light Company

Brunswick Steam Electric Plant  
P. O. Box 10429  
Southport, NC 28461

December 15, 1980

FILE: B09-13516  
SERIAL: BSEP/80-2062

Mr. James P. O'Reilly, Director  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, GA 30303

BRUNSWICK STEAM ELECTRIC PLANT, UNIT NOS. 1 & 2  
LICENSE NOS. DPR-71 AND DPR-62  
DOCKET NOS. 50-325 AND 50-324  
SPECIAL REPORT PER TECHNICAL SPECIFICATION 3.7.8a

Dear Mr. O'Reilly:

On November 17, 1980, a Unit No. 2 fire barrier LCO was generated on two inoperable fire doors in the Diesel Generator Building to allow their repair and return to normal operable status. Unfortunately, due to an unavailability of replacement hardware, needed to repair the doors, the LCO time frame has been exceeded. Fire door DG 125 is presently inoperable due to a worn latching assembly while fire door DG 203 is inoperable due to a worn locking core. Both doors will be returned to normal operability following the receipt of the required replacement hardware.

Very truly yours,

A. C. Tollison, Jr., General Manager  
Brunswick Steam Electric Plant

MJP/mew

cc: Mr. R. A. Hartfield  
Mr. V. Stello, Jr. ✓

8012220349

.5

A002  
5/10