



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

NOV 13 1980

Central Files
NOV 13 8 PM 1 03
DISTRIBUTION SERVICES
REPRODUCTION UNIT

Stahl Construction Company
ATTN: William Curran - President
3802 N. Stahl Road
DeKalb, IL 60115

License No. 12-17785-01

Gentlemen:

This refers to the routine inspection conducted by Mr. D. G. Wiedeman and Dr. L. W. Shatterly of this office on November 3, 1980, of activities authorized by NRC Byproduct Material License No. 12-17785-01 and to the discussion of our findings with Messrs. J. O'Kane and D. Curran at the conclusion of the inspection.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, independent measurements, and interviews with personnel.

During this inspection, certain of your activities appeared to be in non-compliance with NRC requirements, as described in the enclosed Appendix A.

This notice is sent to you pursuant to the provisions of Section 2.201 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations. Section 2.201 requires you to submit to this office within twenty days of your receipt of this notice a written statement or explanation in reply, including for each item of noncompliance: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further noncompliance; and (3) the date when full compliance will be achieved. Be sure to address each of these items in your response.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

A. B. Davis, Chief
Fuel Facility and
Materials Safety Branch

cc w/encl:
Central Files
Reproduction Unit NRC 20b
NSIC
TIC

8012230 008