

APPENDIX A

NOTICE OF VIOLATION

Metropolitan Edison Company  
Reading, Pennsylvania 19603  
Docket No. 50-289

Based on the results of an NRC inspection conducted on February 17, 18, 22 and 23, 1977, it appears that certain of your activities were not conducted in full compliance with NRC regulations and the conditions of your NRC Facility License No. DPR-50, as indicated below. These items are categorized as Deficiencies.

- A. Section 4.4.a and Table 3 of the Environmental Technical Specifications (ETS) require, in part, that air particulates be sampled and analyzed on a weekly basis at each of the specified locations.

Contrary to these requirements, air particulates were not sampled and analyzed for one of these specified locations, 9G1, during 10 successive weeks from March 25 to June 3, 1976.

- B. Section 4.4.a and Table 3 of the ETS require, in part, that sediment samples be analyzed with sufficient analytical sensitivity so as to meet the minimum sensitivity requirements specified in Table 3.

Contrary to these requirements, the required sediment samples collected in July 1976 were not analyzed with sufficient sensitivity to meet the specified minimum sensitivities for Sr-89 and for Sr-90.

- C. Section 4.4.a and Table 3 of the ETS require, in part, that water samples collected at the City of Columbia water intake be analyzed with sufficient sensitivity to meet the minimum analytical sensitivities specified in Table 3.

Contrary to these requirements, the water samples collected from the City of Columbia water intake during the Third Quarter, 1976, were not analyzed with sufficient sensitivity to meet the specified minimum sensitivity for Sr-89.

1582 343

7911110073