



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

~~PDR~~
TERA

OCT 1 1979

Picker Corporation
ATTN: Mr. J. B. Stickney
Chairman, Radioisotope
Committee
595 Miner Road
Cleveland, OH 44143

License No. 34-07225-09

Gentlemen:

This refers to the inspection conducted by Mr. W. H. Schultz of this office on August 14, 1979, of activities authorized by NRC Byproduct Material License No. 34-07225-09 and to the discussion of our findings with Messrs. Robert W. Arndt and Clarence A. Pengov at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No items of noncompliance with NRC requirements were identified during the course of this inspection.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC's Public Document Room, except as follows. If this report contains information that you or your contractors believe to be proprietary, you must apply in writing to this office, within twenty days of your receipt of this letter, to withhold such information from public disclosure. The application must include a full statement of the reasons for which the information is considered proprietary, and should be prepared so that proprietary information identified in the application is contained in an enclosure to the application.

2017 174

7911130 214

OCT 1 1979

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

J. A. Pagliaro

J. A. Pagliaro, Chief
Materials Radiological
Protection Section 2

Enclosure: IE Inspection
Report No. 03005741/79-01

cc w/encl:
Central Files
Reproduction Unit NRC 20b
PDR
NSIC

2017 175