

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401
400 Chestnut Street Tower II

January 18, 1980

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

HARTSVILLE AND PHIPPS BEND NUCLEAR PLANTS - REPORTABLE DEFICIENCY -
INADEQUATE MATERIAL TRACEABILITY ON BERGEN PATERSON COMPONENT SUPPORT
ATTACHMENTS (NCR'S HNP-A-077 AND PBN-051)

Initial notification of the subject reportable deficiency was made to
R. W. Wright on December 12, 1979. In compliance with paragraph 50.55(e),
we are enclosing the final report of the subject deficiency. If you
have any questions regarding this subject, please call Jim Domer at
FTS 854-2014.

Very truly yours,

TENNESSEE VALLEY AUTHORITY



L. M. Mills, Manager
Nuclear Regulation and Safety

Enclosure

cc: Mr. Victor Stello, Director (Enclosure) ✓
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

1791 092

B019
SE
1/1