

## UNITED STATES NUCLEAR REGULATORY COMMISSION

REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

JAN 9 1980

Docket No. 50-454 Docket No. 50-455

Commonwealth Edison Company ATTN: Mr. Cordell Reed Vice President Post Office Box 767 Chicago, IL 60690

## Gentlemen:

Thank you for your interim report dated December 26, 1979, pursuant to 10 CFR 50.55(e) regarding the failure of two (2) field anchorheads for the horizontal tendons used to post-tension the concrete (primary) containments on Byron Units 1 and 2. We will review your final report on this matter upon receipt.

Your cooperation with us is appreciated.

Sincerely,

G. Fiorelli, Chief
Reactor Construction and
Engineering Support Branch

cc: Mr. D. L. Peoples, Director
of Nuclear Licensing
Gunner Sorensen, Site
Project Superintendent
Central Files
Reproduction Unit NRC 20b
PDR
Local PDR
NSIC
TIC
Mr. Dean Mansell, Office of
Assistant Attorney General

1795 139