The



Jersey Central Power & Light Company Madison Avenue at Punch Bowl Road Morristown, New Jersey 07960 (201) 455-8200

December 21, 1979

Mr. Boyce H. Grier, Director Office of Inspection and Enforcement United States Nuclear Regulatory Commission Region I 631 Park Avenue King of Prussia, Pennsylvania 19406

Dear Mr. Grier:

Subject: Oyster Creek Nuclear Generating Station Docket No. 50-219 IE Bulletin No. 79-25

The purpose of this letter is to respond to the directives set forth in IE Bulletin No. 79-25 which is concerned with failures of Westinghouse BFD relays in safety-related systems. No relays of this type are used in the safety-related systems or elsewhere at the Oyster Creek Nuclear Generating Station. IE Bulletin No. 79-25, therefore, does not apply to the Oyster Creek Station. Similar replies concerning the same type relay were provided to your office in respose to IE Bulletin No. 76-05 (April 5, 1976) and IE Circular No. 76-02 (August 18, 1976).

Very truly yours.

Donald A. Ross, Manager Generating Stations-Nuclear

CS

cc: United States Nuclear Regulatory Commission Office of Inspection and Enforcement Division of Reactor Operations Inspection Washington, DC 20555

1795 270

8001 240 35