



**Duquesne Light**

435 Sixth Avenue  
Pittsburgh, Pa.  
15219

(412) 456-6000

December 17, 1979

United States Nuclear Regulatory Commission  
Attention: Mr. Boyce H. Grier, Director  
Region I  
631 Park Avenue  
King of Prussia, Pennsylvania 19406

Reference: Beaver Valley Power Station, Unit No. 1  
Docket No. 50-334  
License No. DPR-66  
Response To IE Bulletin 79-25

Dear Mr. Grier:

We have reviewed IE Bulletin 79-25 concerning failures of Westinghouse BFD relays in safety-related systems. Our review indicates that Westinghouse BFD/NBFD relays are not used to perform safety related functions at the Beaver Valley Power Station.

During our review of this bulletin, we determined that several Westinghouse BFD relays are used in control systems. However, these relays are not the particular BFD relays identified in the Bulletin. We conclude that none of the Westinghouse BFD/NBFD relays identified in the referenced Bulletin are used to perform safety related functions at Beaver Valley. No corrective action is required at this time.

If you have any questions regarding this response, please contact my office.

Very truly yours,

*C. N. Dunn*  
C. N. Dunn  
Vice President, Operations

cc: United States Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Division of Reactor Operations Inspection  
Washington, D. C. 20555

314  
1795 313

8001240 360 Q