

*me*

**PHILADELPHIA ELECTRIC COMPANY**

2301 MARKET STREET  
P.O. BOX 8699  
PHILADELPHIA, PA. 19101

SHIELDS L. DALTROFF  
VICE PRESIDENT  
ELECTRIC PRODUCTION

(215) 841-5001

December 13, 1979

Docket Nos.: 50-277  
50-278

Re: IE Bulletin No. 79-25

Mr. Boyce H. Grier, Director  
Office of Inspection & Enforcement  
Region I  
United States Nuclear Regulatory Commission  
631 Park Avenue  
King of Prussia, PA 19406

Dear Mr. Grier:

This letter is in response to IE Bulletin 79-25 forwarded to us on November 2, 1979, concerning failures of Westinghouse BFD relays in safety related systems. The certain Westinghouse BFD/NBFD relays identified in the Bulletin and listed below are not in use and are not planned for use in safety related systems at Peach Bottom Atomic Power Station:

- a. Type BFD, style 46E7352 or 766A235,  
coil style 503C428G21
- b. Type BFD, style 5069A95, coil style  
1259C71G19
- c. Type BFD, style 5072A49, coil style  
1271C50G01

Should you have any questions or require additional information, please do not hesitate to contact us.

Very truly yours,

*Shields L. Daltroff*

cc: U. S. Nuclear Regulatory Commission  
Office of Inspection & Enforcement  
Divisions of Reactor Operations Inspection  
Washington, DC 20555

1795-350 357

8001240380

Q