

DSB



Wisconsin Electric POWER COMPANY
231 W. MICHIGAN, P.O. BOX 2046, MILWAUKEE, WI 53201

January 9, 1980


Mr. James G. Keppler, Director
Office of Inspection and Enforcement
U. S. NUCLEAR REGULATORY COMMISSION
Region III
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

DOCKET NO. 50-266
POINT BEACH NUCLEAR PLANT, UNIT 1
LICENSEE EVENT REPORT NO. 79-022/01T-0

Enclosed are Licensee Event Report No. 79-022/01T-0 (a 14-day followup report) and an attachment which provide a description of an event reportable in accordance with Technical Specification 15.6.9.2.A.2, "Operation of the unit or affected systems when any parameter or operation subject to a limiting condition for operation is less conservative than the least conservative aspect of the limiting condition for operation established in the Technical Specifications", and 15.6.9.2.A.6, "Personnel error or procedural inadequacy which prevents, or could prevent by itself, the fulfillment of the functional requirements of systems required to cope with accidents analyzed in the FFDSAR".

Very truly yours,


Executive Vice President

Sol Burstein

Enclosure

A002
S
1/1

JAN 14 1980

1794 142

S

8001240 420