TEXAS UTILITIES GENERATING COMPANY

2001 BRYAN TOWER · DALLAS. TEXAS 75201

R. J. GARY EXECUTIVE VICE PRESIDENT AND GENERAL MANAGER

December 19, 1979 TXX-3083

Mr. Karl V. Seyfrit, Director U. S. Nuclear Regulatory Commission Region IV 611 Ryan Plaza Drive, Suite 1000 Arlington, Texas 76012

RIV Docket Nos. 50-445/IE Bulletin No. 79-25 50-446/IE Bulletin Nc. 79-25

TIC.

COMANCHE PEAK STEAM ELECTRIC STATION 1981-83 2300 MW INSTALLATION IE BULLETIN 79-25 FILE NO: 10115

Dear Mr. Seyfrit:

In reference to IE Bulletin 79-25, dated November 2, 1979, concerning failures of Westinghouse BFD relays in safety-related systems, our review is not yet complete.

To date, our Architect-Engineer has determined that no Westinghouse BFD relays are specified in BOP safety-related equipment. We are now following up on our written requests to all relevant vendors, including the NSSS supplier, to assure that the above relays are not used in safety-related equipment.

We request an extension to June 30, 1980 in order to confirm this and implement corrective action as necessary. If there are any questions, please advise.

Very truly yours,

RJG:df

cc: U. S. Nuclear Regulatory Commission Office of Inspection and Enforcement Division of Reactor Operations Inspection Washington, D. C. 20555

11-15

DEC 1975