

APPENDIX A

NOTICE OF VIOLATION

Virginia Electric and Power Company
North Anna 2

License No. CPPR-78

Based on the NRC inspection December 3-21, 1979, certain of your activities were apparently not conducted in full compliance with NRC requirements as indicated below. These items have been categorized as described in correspondence to you dated December 31, 1974.

As required by Criterion XVI of Appendix B to 10 CFR 50, conditions adverse to quality shall be documented and identified to appropriate levels of management. Paragraph 6.1 of Section 5.13 of Virginia Electric and Power Company's (VEPCO) Quality Assurance Manual, Engineering and Construction, requires that each suspected failure to comply with the Atomic Energy Act or with NRC rules, orders, or licenses, and each deviation be reported on Form #883.8C. The VEPCO employee, VEPCO architect-engineer, constructor, NSS vendor or consultant who discovers the suspected failure or deviation shall immediately forward the information to the Project Engineer, or his designee, for completion of Part 1 of Form #883.8C. Upon completion, a copy shall be hand carried to the Executive Manager Licensing and Quality Assurance or his designee. Additionally, Paragraph 6.2 of Section 5.13 requires that reviews be completed within five (5) calendar days or items become automatically reportable.

Contrary to the above, information concerning problems reported on Unit 1 as LER's 79-143 on November 9, 1979 and 79-152 and 79-153 on November 16, 1979, had not been reviewed for applicability to Unit 2 as of December 4, 1979.

This is an Infraction. Similar items were brought to your attention in our letters dated June 25 and August 7, 1979.

~~8003050352~~
8003050352