

Northern Indiana Public Service Company

General Offices | 5265 Hohman Avenue | Hammond, Indiana 46325 | Tel.: 853-5200 (219)

EUGENE M. SHORB

February 14, 1980

Mr. James G. Keppler, Regional Director U. S. Nuclear Regulatory Commission Region III 799 Roosevelt Road Glen Ellyn, Illinois 60137

Re: NRC IE Bulletin 79-28, "Possible Malfunction of NAMCO Model EA180 Limit Switches At Elevated Temperatures," dated December 7, 1979 - Docket No. 50-367

Dear Mr. Keppler:

This letter is in response to IE Bulletin No. 79-28 dated December 7, 1979. We have determined, through correspondence with our NSSS vendor and architect/engineer, that NAMCO Model EA-180 limit switches described in the referenced IE Bulletin have not been and will not be installed on any safety-related equipment located inside or outside containment, including valve position indicating circuitry related to containment isolation valves.

Very truly yours,

Tilthub

EMS:cgs .

cc: U. S. Nuclear Regulatory Commission Office of Inspection & Enforcement Division of Reactor Construction Inspection Washington, D.C. 20555