



UNITED STATES  
NUCLEAR REGULATORY COMMISSION

REGION IV  
611 RYAN PLAZA DRIVE, SUITE 1000  
ARLINGTON, TEXAS 76012

17 OCT 1980

*central  
files*

REGULATORY SERVICES  
BRANCH

1980 NOV 17 PM 1 09

REGULATORY SERVICES  
BRANCH

License No. 43-03227-01

Thiokol Corporation  
Attn: Mr. J. W. Loosle  
Division Manager  
Wasatch Division  
Brigham City, Utah 84302

Gentlemen:

This refers to the inspection conducted by Mr. C. L. Cain of this office on October 7, 1980, of the activities authorized by NRC Byproduct Material License No. 43-03227-01 and to the discussion of our findings held by Mr. Cain with Mr. L. G. Koch on October 7, 1980.

The inspection was an examination of the activities conducted under the license as they relate to radiation safety and to compliance with the Commission's rules and regulations, and the conditions of the license. The inspection consisted of selective examinations of procedures and representative records, interviews of personnel, independent measurements and observations by the inspector.

No items of noncompliance with NRC requirements were found during the inspection.

Mr. Cain also reviewed the action you had taken with respect to one item of noncompliance observed during our previous inspection, which was conducted May 11, 1978. He verified that the corrective action with respect to this item was implemented as stated in your reply of June 8, 1978 to our letter dated May 23, 1978.

Should you have any questions concerning this letter, please let me know.

Sincerely,

Glen D. Brown, Chief  
Fuel Facility and Material  
Safety Branch