

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

400 Chestnut Street Tower II

February 12, 1980

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

SEQUOYAH NUCLEAR PLANT UNITS 1 AND 2 - PIPING EMBEDDED IN STRUCTURAL
CONCRETE - NCR CEB 79-1 - SUPPLEMENTAL INFORMATION

The subject deficiency was initially reported to NRC-OIE Inspector
A. Herdt on January 12, 1979, in accordance with 10 CFR 50.55(e).
An interim report was submitted on February 8, 1979, and a final
report was submitted on March 21, 1979. Enclosed is our revised
final report. This revision has been made to provide supplemental
information on the description of the nonconformance.

If you have any questions concerning this matter, please get in touch
with D. L. Lambert at FTS 854-2581.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager
Nuclear Regulation and Safety

Enclosure

cc: Mr. Victor Stello, Jr., Director (Enclosure) ✓
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

B019
S-11

8002190 563