

# LICENSEE EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	M	A	P	P	S	1	0	0	-	0	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4	5
7	8	9	LICENSEE CODE				14	15	LICENSE NUMBER								25	26	LICENSE TYPE				30	57	CAT	58	

0	1	L	0	5	0	-	0	2	9	3	0	1	1	5	8	0	0	2	0	7	8	0	9
7	8	REPORT SOURCE		60	61	DOCKET NUMBER				68	69	EVENT DATE				74	75	REPORT DATE				80	

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 On January 15, 1980 while performing a snubber inspection, the strut bushing insert

0 3 on RHR System snubber number SS-10-10-46 was determined to be turning freely within

0 4 its strut. The snubber is located in an accessible area within the torus room. The

0 5 snubber was repaired and returned to service. The snubber surveillance interval will

0 6 be reduced as required by PNPS Technical Specifications as a result of this event.

0 7

0 8

0 9

0	9	C	F	A	Z	S	U	P	O	R	T	X	Z		
7	8	SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE				COMP SUBCODE		VALVE SUBCODE	

17	8	0	0	0	6	0	3	L	0				
7	8	LER/RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.	

B	Z	Z	Z	0	0	0	0	N	N	A	B	2	0	9	
33	34	35	36	HOURS				40	41	NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 A strut to strut bushing weld was performed to restore the snubber to operable status.

1 1 The lack of this weld allowed the snubber to slide freely within its supporting strut.

1 2 The installation of this snubber and subsequent inspections, although noting an un-

1 3 usually long snubber stroke, failed to detect this defect. Safety related snubbers

1 4 at PNPS have been inspected and we are confident that this is an isolated case.

1	5	H	0	0	0	N.A.	B	Routine Test/Inspection	
7	8	FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY	

1	6	Z	Z	N.A.	N.A.
7	8	ACTIVITY CONTENT RELEASED OF RELEASE		AMOUNT OF ACTIVITY	

1	7	0	0	0	Z	N.A.	
7	8	PERSONNEL EXPOSURES NUMBER		TYPE		DESCRIPTION	

1	8	0	0	0	N.A.
7	8	PERSONNEL INJURIES NUMBER		DESCRIPTION	

1	9	Z	N.A.		
7	8	LOSS OF OR DAMAGE TO FACILITY TYPE		DESCRIPTION	

2	0	N	N.A.		
7	8	PUBLCITY ISSUED		DESCRIPTION	

8002200 652