



**LOUISIANA**  
**POWER & LIGHT**

142 DELARONDE STREET  
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

January 30, 1980

D. L. ASWELL  
Vice President-Power Production

LPL 12968  
Q-3-A35.07.13  
3-A1.01.04

Mr. K. V. Seyfrit, Director, Region IV  
U. S. Nuclear Regulatory Commission  
Office of Inspection & Enforcement  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76012

SUBJECT: Waterford SES Unit No. 3  
Docket No. 50-382  
Status - Significant Construction  
Deficiency No. 13, "Reactor  
Containment Building Dome"

References: (1) LP&L Letter LPL 11994 dated September 14, 1979; Interim Report  
(2) LP&L Letter LPL 12376 dated November 28, 1979; Suppl. No. 1 to  
Interim Report

Dear Mr. Seyfrit:

The final report submittal date of February 1, 1980, for subject deficiency will not be met due to ongoing verification testing of the repaired areas. Repair of all areas is now complete with verification testing to assure structural integrity the only remaining activity.

The final report for this deficiency will now be issued no later than April 15, 1980.

Very truly yours,

D. L. Aswell

DLA:JMR:dmk

cc: 1) Director  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

2) Director  
Office of Management  
Information and Program Control  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

8002200

754