



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
REGION III  
799 ROOSEVELT ROAD  
GLEN ELLYN, ILLINOIS 60137

PDR

FEB 8 1980


Docket No. 50-546  
Docket No. 50-547

Public Service of Indiana  
ATTN: Mr. S. W. Shields  
Vice President - Electric  
System  
1000 East Main Street  
Plainfield, IN 46168

Gentlemen:

Thank you for your interim report dated January 24, 1980, pursuant to 10 CFR 50.55(e) regarding several joints in safety related structural steel located in the auxiliary building which had not been bolted properly. We will review your final report on this matter upon receipt.

Sincerely,

  
for G. Fiorelli, Chief  
Reactor Construction and  
Engineering Support Branch

cc: C. Kammerer, CA  
H. Thornburg, IE  
Mr. G. N. Brown, Project  
Director  
Central Files  
Reproduction Unit NRC 20b  
PDR  
Local PDR  
NSIC  
TIC  
LeBoeuf, Lamb, Leiby & MacRae  
Mr. Dave Martin, Office of  
Attorney General  
Mr. John Galloway, Staff  
Director, Environment, Energy  
and Natural Resources Subcommittee

8002260 056