

THE TENNESSEE VALLEY AUTHORITY

KNOXVILLE, TENNESSEE 37902

716 Edney Building

FEB 22 1980

Mr. James P. O'Reilly, Director  
U.S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 1 - DOCKET  
NO. 50-259 - FACILITY OPERATING LICENSE DPR-33 - REPORTABLE OCCURRENCE  
REPORT BPRO-50-259/8009

The enclosed report provides details concerning Surveillance Instruction  
4.2.A-10, Reactor Building Radiation Monitoring, which was not performed  
by January 4, 1980, as scheduled, but was performed three weeks later.  
This report is submitted in accordance with Browns Ferry unit 1 Technical  
Specification 6.7.2.b.3.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

J. R. Calhoun  
Director of Nuclear Power

Enclosure (3)

cc (Enclosure):

Director (3)  
Office of Management Information and Program Control  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

Director (40)  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

Mr. Bill Lavalley  
Nuclear Safety Analysis Center  
Palo Alto, California 94303

Mr. R. F. Sullivan, NRC Inspector, Browns Ferry

8002260

645

App 2  
2/11