



435 Sixth Avenue
Pittsburgh, Pa.
15219

(412) 456-6000

February 20, 1980

United States Nuclear
Regulatory Commission
Region I
631 Park Avenue
King of Prussia, PA 19406

ATTENTION: Mr. Robert T. Carlson, Chief
Reactor Construction and
Engineering Support Branch

Gentlemen:

SUBJECT: Beaver Valley Power Station Unit No. 2
Docket No. 50-412
Infraction No. 79-09-01
Cable Tray Separation-Drawing Review

This letter is a response to a NRC letter dated January 16, 1980 concerning an audit at the Beaver Valley Unit #2 jobsite on December 11-13, 1979 which resulted in Infraction No. 79-09-01 (cable tray barriers).

As a result of the infraction, all Category I cable tray drawings were reviewed for conformance to the required separation criteria. The following plan drawings were found to be not in conformance with these criteria:

12241-RE-34A
12241-RE-34AG
12241-RE-34AH
12241-RE-34B


12241-RE-34D
12241-RE-34F
12241-RE-34G

All the above plan drawings and associated section drawings were updated by interim revision as of January 15, 1980.

In order to avoid further items of noncompliance, project procedure 2BVM-41 is being revised to require that the Engineers will review final safety related cable tray drawings for conformance to barrier requirements on a schedule to support tray cover installation, which is the latest time for barriers to be installed.

DUQUESNE LIGHT COMPANY

By:


E. J. Woolever
Vice President

cc: Messrs. V. Stello (15)
W. G. McDonald

8002270403