



ARKANSAS POWER & LIGHT COMPANY  
POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000

February 22, 1980

2-020-13

Mr. K. V. Seyfrit, Director  
Office of Inspection & Enforcement  
Region IV  
U. S. Nuclear Regulatory Commission  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76011

Subject: Arkansas Nuclear One-Unit 2  
Docket No. 50-368  
License No. NPF-6  
Licensee Event Report Nos.  
80-007/03L-0 and 80-008/03L-0  
(File: 2-0520)

Gentlemen:

In accordance with Arkansas Nuclear One-Unit 2 Technical Specification 6.9.1.9.b, attached are the subject reports concerning a low level in the Sodium Hydroxide Tank (80-007/03L-0) and a Core Protection Calculator channel failure (80-008/03L-0).

Very truly yours,

*David C. Trimble*

David C. Trimble  
Manager, Licensing

DCT:MAS:sh  
Attachments

cc: Victor Stello, Jr., Director  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Mr. W. D. Johnson  
U. S. Nuclear Regulatory Commission  
P. O. Box 2090  
Russellville, Arkansas 72801

Norman M. Haller, Director  
Office of Management & Program Analysis  
U. S. Nuclear Regulatory Commission  
Washington, D.C. 20555