

# LICENSEE EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_ 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 I L D R S 3 2 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5  
9 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE 1 JO 57 CAT 58

CON'T  
0 1 REPORT SOURCE L 6 0 5 0 0 0 2 4 9 7 0 2 1 3 8 0 3 0 2 2 5 8 0 9  
8 60 81 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

### EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

0 2 While in the S/D mode of operation the MSIV scram limit switches were checked. Of  
0 3 the 16 limit switches 2 were found to have setpoints > 10%. This event was of minimal  
0 4 safety significance since the MSIV's with limit switch setpoints > 10% also had a re-  
0 5 dundant MSIV in the same line with limit switch setpoints of < 10% as required by Tech.  
0 6 Spec. Table 3.1.1. This type of event has occurred before at Dresden. (See RO#79-57/  
0 7 OIT-0, Docket #050-237).

0 9 SYSTEM CODE I A 11 CAUSE CODE B 12 CAUSE SUBCODE C 13 COMPONENT CODE I N S T R U 14 COMP. SUBCODE S 15 VALVE SUBCODE Z 16  
9 9 10 11 12 13 14 15 16  
17 LER/RO REPORT NUMBER 8 0 21 22 23 24 25 26 27 28 29 30 31 32  
EVENT YEAR 8 0 21 22 23 24 25 26 27 28 29 30 31 32  
ACTION TAKEN E 18 Z 19 FUTURE ACTION Z 20 EFFECT ON PLANT Z 21 SHUTDOWN METHOD Z 22 HOURS 0 0 0 0 0 22 ATTACHMENT SUBMITTED Y 23 NPRO-4 FORM SUB. N 24 PRIME COMP. SUPPLIER N 25 COMPONENT MANUFACTURER N 0 1 5 26  
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

### CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

1 0 The Namco Snap Lock limit switch setpoints were set by the manufacturer. The need for  
1 1 field calibration of the exact limit switch trip point did not seem necessary at the  
1 2 time of installation. The limit switches were readjusted and demonstrated operable.  
1 3 No further action is necessary.

1 5 FACILITY STATUS H 28 % POWER 0 0 0 29 OTHER STATUS NA 30 METHOD OF DISCOVERY D 31 DISCOVERY DESCRIPTION External Source-Quad Cities 32  
8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 6 ACTIVITY CONTENT Z 33 Z 34 AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE NA 36  
8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 7 PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION NA 39  
8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 8 PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION NA 41  
8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 9 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA 43  
8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

2 0 PUBLICITY ISSUED N 44 DESCRIPTION NA 45  
8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

NRC USE ONLY