

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	C	B	E	P	2	0	0	-	0	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4	5					
7	8	9	LICENSEE CODE						14	15	LICENSE NUMBER										25	26	LICENSE TYPE					30	57	CAT	58	9

0	1	L	0	5	0	-	0	3	2	4	7	0	2	1	2	8	0	8	0	3	1	2	8	0	9	
7	8	REPORT SOURCE		60	61	DOCKET NUMBER					68	69	EVENT DATE					74	75	REPORT DATE					80	9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | While performing PT 2.1.8PC, RCIC Exhaust Diaphragm Calibration and Functional

0 3 | Test, RCIC exhaust diaphragm high pressure switches E51-PS-N012A&C actuated at

0 4 | 11.9 psig. The reportable limit for these switches is ≥ 10 psig.

0 5 | _____

0 6 | _____

0 7 | _____

Technical Specifications 3.3.2, 6.9.1.9b

0	9	C	F	E	E	I	N	S	T	R	U	S	Z	
7	8	SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE				COMP. SUBCODE	VALVE SUBCODE	
9	10	11	12	13	18	19	20							
17	LER RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.			
21	22	23	24	25	26	27	28	29	30	31	32			
E	Z	Z	Z	HOURS			ATTACHMENT SUBMITTED		NPRD-4 FORM SUB		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER	
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | The reason for the actuation setpoint being out of calibration is attributed to

1 1 | instrument drift. The switches were recalibrated and returned to service. A

1 2 | functional check is performed on these switches every month and a calibration

1 3 | performed every 18 months. The frequency for the calibration has been changed

1 4 | to every six months. This should prevent recurrence.

1	5	E	0	8	0	N/A	B	Periodic Test	
7	8	FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY	DISCOVERY DESCRIPTION
9	10	11	12	13	30	44	45	46	32

1	6	Z	Z	N/A	N/A	
7	8	ACTIVITY RELEASED		AMOUNT OF ACTIVITY		LOCATION OF RELEASE
9	10	11	12	13	35	36

1	7	0	0	0	Z	N/A
7	8	PERSONNEL EXPOSURES		DESCRIPTION		
9	10	11	12	13	37	38

1	8	0	0	0	N/A	
7	8	PERSONNEL INJURIES		DESCRIPTION		
9	10	11	12	13	40	41

1	9	Z	N/A			
7	8	LOSS OF OR DAMAGE TO FACILITY		DESCRIPTION		
9	10	11	12	13	43	44

2	0	N	N/A			
7	8	PUBLICITY ISSUED		DESCRIPTION		
9	10	11	12	13	45	46

NAME OF PREPARER A. C. Tollison, Jr.

PHONE: 919-457-9521

8003180418