



ARKANSAS POWER & LIGHT COMPANY  
POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000  
March 13, 1980

2-030-07

Mr. K. V. Seyfrit, Director  
Office of Inspection & Enforcement  
Region IV  
U. S. Nuclear Regulatory Commission  
622 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76011

Subject: Arkansas Nuclear One - Unit 2  
Docket No. 50-368  
License No. NPF-6  
Licensee Event Report Nos.  
80-010/03L-0, 80-011/03L-0,  
and 80-012/03L-0  
(File: 2-0520)

Gentlemen:

In accordance with Arkansas Nuclear One - Unit 2 Technical Specification 6.9.1.9.b,c, and d, attached are the subject reports concerning the failure to perform the 24 month local leak rate requirements (80-011/03L-0), five containment penetrations leak rates exceeding limits (80-011/03L-0) and the Diesel Generator unit becoming inoperable (80-012/03L-0).

Very truly yours,

*David C. Trimble*  
David C. Trimble  
Manager, Licensing

DCT:GAC:sh  
Attachment

cc: Mr. Victor Stello, Jr., Director  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington D. C. 20555

Mr. W. D. Johnson  
U. S. Nuclear Regulatory Commission  
P. O. Box 2090  
Russellville, Arkansas 72801

Mr. Norman M. Haller, Director  
Office of Management & Program Analysis  
U. S. Nuclear Regulatory Commission  
Washington D. C. 20555