

DAIRYLAND POWER COOPERATIVE

La Crosse, Wisconsin

54601

December 17, 1979

In reply, please
refer to LAC-6690

DOCKET NO. 50-409

Mr. James G. Keppler
Regional Director
U. S. Nuclear Regulatory Commission
Directorate of Regulatory Operations
Region III
799 Roosevelt Road
Glen Ellyn, Illinois 60137

SUBJECT: DAIRYLAND POWER COOPERATIVE
LA CROSSE BOILING WATER REACTOR (LACBWR)
PROVISIONAL OPERATING LICENSE NO. DPR-45
IE BULLETIN NO. 79-28 - POSSIBLE MALFUNCTION
OF NAMCO MODEL EA180 LIMIT SWITCHES AT
ELEVATED TEMPERATURES

Reference: (1) NRC Letter, Keppler to Linder,
dated December 10, 1979.

Dear Mr. Keppler:

In response to your letter (Reference 1) containing IE Bulletin
No. 79-28, we have determined the following:

- 1) NAMCO EA180 switches, i.e., dated code, February 2,
1979 through August 24, 1979, are not used or planned
to be used in safety or non-safety related circuits
at the LACBWR facility, including circuitry related
to containment isolation valves.

If there are any questions concerning this response, please contact
us.

Very truly yours,

DAIRYLAND POWER COOPERATIVE

Frank Linder
Frank Linder, General Manager

FL:WRN:af

cc: U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Division of Reactor Operation Inspection
Washington, D. C. 20555

JAN 23 1980

8003190141