



USNRC REGIONAL
ATLANTA, GEORGIA

**Florida
Power**
CORPORATION

00 JAN 24 AIO: 45

21 January 1980
3-0-3-a-2
CS-80-25

Mr. J. P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
101 Marietta St., Room 3100
Atlanta, Georgia 30303

Docket No. 50-302
Licensee No. DPR-72
Ref: RII:SAE
50-302/79-52

Dear Mr. O'Reilly:

We offer the following response to the apparent Deviation in the referenced inspection report.

NOTICE OF DEVIATION

Branch Technical Position APCS 9.5-1, Appendix A, Section C.6 requires in part that "Fire extinguishers should be provided in accordance with guidelines of NFPA 10 and 10A, "Portable Fire Extinguishers, Maintenance and Use." The Fire Protection Program Review, Crystal River Unit 3, dated June 1979 and submitted to the NRC states in part in Section 6.E.6 that "the (above) requirement is met. Fire extinguishers are provided in accordance with NFPA 10."

Contrary to the above, surveillance procedures for portable fire extinguishers SP-800, revision 3 and SP-801, revision 1 do not reference NFPA-10 or the inspection and maintenance sections therein and do not contain all of the checks and acceptance criteria used in NFPA 10.

Response: Surveillance procedures SP-800 and SP-801 have been revised to reference NFPA-10 and appendices. These revisions include all applicable checks used in NFPA-10 by major groups. These groups are not specifically delineated within the body of the procedure as they are subject to change. "Initial" and "date" blanks have been provided for each check list step and a "disposition" column covering retirements/repairs was added to SP-800. Complete implementation of these revisions and full compliance will be achieved by February 1, 1980. Should there be further questions, please contact us.

Very truly yours,

FLORIDA POWER CORPORATION

W.C. Poole
Nuclear Plant Mngr.

J. A. Hancock
J. A. Hancock
Director, Nuclear Operations

JC/tb

8003190658

8034