

LICENSEE EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01	C	0	F	S	V	1	2	0	0	-	0	0	0	0	0	0	0	0	0	3	4	1	1	2	0	4	5			
7	8	9	LICENSEE CODE						14	15	LICENSE NUMBER										25	26	LICENSE TYPE				30	57	CAT 58	

01	L	8	0	5	0	0	0	2	6	7	7	0	2	1	8	8	0	8	0	3	1	9	8	0	9		
7	8	9	REPORT SOURCE				60	61	DOCKET NUMBER						68	69	EVENT DATE				74	75	REPORT DATE				80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | On February 18, 1980, with the reactor critical at less than 2% power, it was

03 | determined that a vent stack snubber, VSS-117, was inoperable and a degraded mode of

04 | Fort St. Vrain Technical Specification LCO 4.3.10 existed. This is reportable per

05 | Fort St. Vrain Technical Specification AC 7.5.2(b)3. The reactor was taken sub-

06 | critical and remained subcritical till the snubber was replaced. No accompanying oc-

07 | currence. No affect on public health or safety. A similar occurrence was RO 79-64.

08 | \_\_\_\_\_

09	A	A	11	A	12	C	13	S	U	P	O	R	T	14	D	15	Z	16									
7	8	9	SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE					COMP. SUBCODE		VALVE SUBCODE											
17	8	0	21	22	23	0	0	6	24	25	26	27	0	3	28	29	L	30	31	0	32						
LER/RO REPORT NUMBER		EVENT YEAR		SHUTDOWN METHOD		SEQUENTIAL REPORT NO.		HOURS		ATTACHMENT SUBMITTED		OCCURRENCE CODE		REPORT TYPE		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		REVISION NO.		COMPONENT MANUFACTURER					
33	H	18	Z	19	Z	20	Z	21	0	0	0	0	22	Y	23	0	3	28	N	24	A	25	I	2	0	7	26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 | VSS-117, a vent stack snubber, was removed from service during a maintenance shut-

11 | down without informing the Shift Supervisor. On February 17, 1980, the reactor was

12 | taken critical with operations personnel unaware that VSS-117 had been removed.

13 | Personnel involved were reprimanded and the importance of following approved pro-

14 | cedures re-emphasized. No other corrective action anticipated or required.

15	C	28	0	0	1	29	N/A	30	A	31	Plant Personnel Observation	32
7	8	9	FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
16	Z	33	Z	34	N/A	35	N/A	36	N/A	37	N/A	38
7	8	9	ACTIVITY CONTENT		RELEASED OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE		PERSONNEL EXPOSURES	
17	0	0	0	37	Z	38	N/A	39	0	0	0	40
7	8	9	PERSONNEL EXPOSURES		PERSONNEL INJURIES		LOSS OF OR DAMAGE TO FACILITY		PUBLICITY		ISSUED	
18	0	0	0	40	N/A	41	N/A	42	N/A	43	N/A	44
7	8	9	PERSONNEL INJURIES		LOSS OF OR DAMAGE TO FACILITY		PUBLICITY		ISSUED		DESCRIPTION	
19	Z	42	N/A	43	N/A	44	N/A	45	N/A	46	N/A	47
7	8	9	LOSS OF OR DAMAGE TO FACILITY		PUBLICITY		ISSUED		DESCRIPTION		NAME OF PREPARER	
20	N	44	N/A	45	N/A	46	N/A	47	N/A	48	N/A	49
7	8	9	PUBLICITY		ISSUED		DESCRIPTION		NAME OF PREPARER		PHONE	

800 325 537

NAME OF PREPARER

PHONE: (303) 785-2253