

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

400 Chestnut Street Tower II

50-518

March 19, 1980

Mr. James P. O'Reilly, Director  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Region II - Suite 3100  
101 Marietta Street  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

HARTSVILLE NUCLEAR PLANT UNITS A1 AND B1 - REPORTABLE DEFICIENCY -  
CONTAINMENT ANCHOR BOLT CHAIR WELD DEFICIENCIES (NCR HNP-A-062)

Initial report of the subject reportable deficiency was made to P. S. Cantrell, NRC-OIE, Region II, on August 2, 1979. The first and second interim reports were submitted on August 30, 1979, and January 11, 1980, respectively. In compliance with paragraph 50.55(e) of 10 CFR Part 50, we are enclosing the third interim report of the subject deficiency. It is anticipated that the final report will be transmitted to you on or before July 23, 1980. If you have any questions concerning this subject, please call Jim Domer at FTS 854-2014.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager  
Nuclear Regulation and Safety

Enclosure

cc: Mr. Victor Stello, Director (Enclosure) ✓  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

3019  
SE  
1/1

S

800 200 646