

LICENSEE EVENT REPORT

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	C	B	E	P	1	(2)	0	0	-	0	0	0	0	-	0	0	(3)	4	1	1	1	1	(4)			(5)
7	8	9					14	15										25	26					30		57	CAT	58
		LICENSEE CODE						LICENSE NUMBER										LICENSE TYPE										

CON'T

REPORT SOURCE L 6 0 5 0 - 0 3 2 5 7 0 2 2 7 8 0 8 0 3 2 4 8 0 9

60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 During normal plant operation, the control operator noticed that the primary contain-

0 3 ment gaseous monitor CAC-AQH-1260-3, model 5C-2B, had an unexplained shift from 1000

0 4 cpm to 60 cpm. The gaseous monitors CAC-AQH-1261-3 and 1262-3 were also inoperable.

0 5

0 6

0 7

0 8 Technical Specifications 3.4.3.1c, 6.9.1.9.b

SYSTEM CODE C I 11		CAUSE CODE E 12		CAUSE SUBCODE E 13		COMPONENT CODE I N S T R U 14				COMP. SUBCODE E 15		VALVE SUBCODE Z 16					
EVENT YEAR 8 0 21 22		SEQUENTIAL REPORT NO. 0 1 7 24 26		OCCURRENCE CODE 0 3 28 29		REPORT TYPE L 30		REVISION NO. 0 32									
ACTION TAKEN X 18		FUTURE ACTION X 19		EFFECT ON PLANT Z 20		SHUTDOWN METHOD Z 21		HOURS 0 0 0 0 22		ATTACHMENT SUBMITTED N 23		NPRD-4 FORM SUB. Y 24		PRIME COMP. SUPPLIER N 25		COMPONENT MANUFACTURER N 3 0 5 26	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | Water was found in the detector chamber. The detector was dried, recalibrated, and

1 1 | returned to service satisfactorily. Engineering is investigating a solution to

1 2 | correct the sample flow moisture problem or to replace the instruments with a more

1 3 | dependable type, as this is a recurring problem. These monitors undergo calibration

1 4 | and preventative maintenance every two weeks.

8 9
FACILITY STATUS % POWER OTHER STATUS (30)
1 5 E (28) 0 9 9 (29) N/A
7 8 9 10 11 12 13 44
METHOD OF DISCOVERY DISCOVERY DESCRIPTION (32)
A (31) Operator Surveillance
45 46 80
ACTIVITY CONTENT
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35)
1 6 Z (33) Z (34) N/A
7 8 9 10 11 44
LOCATION OF RELEASE (36)
N/A
45 80

PERSONNEL EXPOSURES									
NUMBER				TYPE	DESCRIPTION				
1	7	0	0	0	Z	N/A			

PERSONNEL INJURIES
NUMBER DESCRIPTION (41)

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50

LOSS OF OR DAMAGE TO FACILITY (43)
TYPE DESCRIPTION
1 9 Z (42) N/A

PUBLICITY ISSUED DESCRIPTION (45)

(2) (0) (N) (44) N/A

NRC USE ONLY

NAME OF PREPARER A. C. Tollison, Jr.

PHONE: (919) 457-9521

8003310 350