



METROPOLITAN EDISON COMPANY SUBSIDIARY OF GENERAL PUBLIC UTILITIES CORPORATION

POST OFFICE BOX 400 MIDDLETOWN, PENNSYLVANIA 17057 TELEPHONE 717-944-4041

*DK Section
7/12*

September 20, 1974

Mr. J.P. O'Reilly, Director
Directorate Of Regulatory
Region I
631 Park Avenue
King Of Purssfa, Pa. 19405

**POOR
ORIGINAL**

Operating License DPR-50
Docket 50-283

Subject: Abnormal Occurrence No. AD 74-17

Dear Mr. O'Reilly:

This telegram is to confirm the conversation between Bert Davis (Region I-AEC), and T.S. Baer (TMI-Engineer, Sr.) at 1515 hrs. 19 September 1974.

The following report is submitted in accordance with paragraph 6.7.2.a.4 (page 6-11) of the technical specifications.

On 19 September 1974, while performing routine surveillance required by table 4.1-3 (page 4-9) of the technical specifications, it was found that the Sodium Hydroxide Tank contained 17,677 pounds of sodium hydroxide in violation of Technical Specification 3.3.1.3.b.

Sodium hydroxide was subsequently drained from the tank in an amount sufficient to insure compliance with technical specification 3.3.1.3.b.

Very truly yours,

J.G. Harboin
J.G. Harboin
Station Superintendent
TMI Nuclear Station

JGI/can

730
7910280

*AKO
2
5*