

## METROPOLITAN EDISON COMPANY CONTINUES OF SENERAL FURLIL STRUCTURES CORFORATION.

January 12, 1978

Mr. Bruce H. Grier Directorate of Regulatory Operation Region =1 Nuclear Regulatory Cormission 630 Park Avenue King of Prussia, PA 19406



Operating License DPR-50 Docket 50-289

Subject: Reportable Occurrence No. 78-2/1P

Dear Mr. Grier:

This telegram is to document the conversation between Mr. P. J. Kellogg. (NRC Inspector) and Mr. J. P. O'Hanlon (TMI-I Superintendent) at 1045 hours on January 12, 1978.

A violation of the Technical Specification 3.18.3.2.a was recognized at 0730 on January 12, 1978, in that a continuous fire watch was not established for a period of about 63 hours after the "A" Emergency Diesel Room Sprinkler Isolation Valve was closed. This incident is considered Reportable under I.S. 6.9.2A.2.

FS-V-156 was closed at about 0500 on January 10, 1978, but due to a incorrect interpretation of the recently issued Fire Service Technical Specification, only a periodic diesel room fire inspection was made until about 1030 on January 12, 1978, at which time a continuous fire watch was established.

Further details of this incident and the corrective actions taken will be forwarded to you in the 14 day report.

Very truly yours,

O P T A oul,

J. P. O'Hanlon

Holinian

- unit - uerintendent

JPO:dws

With the second second

7910250 743

2