

*DK Central
Files*

METROPOLITAN EDISON COMPANY SUBSIDIARY OF GENERAL PUBLIC UTILITIES CORPORATION

OFFICE BOX 489 MIDDLETOWN, PENNSYLVANIA 17057 TELEPHONE 717-944-4041

December 2, 1974

**POOR
ORIGINAL**

Mr. J.P. O'Reilly, Director
Directorate of Regulatory
Region I
631 Park Avenue
King of Prussia, Pa. 19405

Operating License OPR-50
Basket 50-259

Subject: Abnormal Occurrence No. A3 74-27

Dear Mr. O'Reilly:


This letter is to confirm a conversation between Les Spassard (Region I-AEC), and J.G. Harbain (T&E-Station Superintendent) at 1403 hours 2 December 1974.

The following report is submitted in accordance with paragraph 6.7.2.a.5 (page 6-11) of the technical specifications.

Technical specifications require the resilient seal of the personnel air lock outer door to be tested after each use but no more than once daily. The personnel air lock was opened on November 20, 23, 27, 28, and 29, 1974; however, the required testing was not performed.

The resilient seal of the personnel air lock outer door was satisfactorily tested on November 30, 1974.

Procedural steps will be initiated to prevent future occurrences.

Very truly yours,

J.G. Harbain
Station Superintendent

JCI/dm

7910260470

5