

SEP 14 1974

Letter from Duke Power Company, A. C. Thies, dated September 5, 1974 -
ROB 74-9 - 50-269, 50-270 and 50-287

DISTRIBUTION:

H. D. Thornburg;

RO:HQ (4)

Directorate of Licensing (4)

DR Central Files

John Rizzo, OOE

PDR

Local PDR

NSIC

TIC

7912110 839

Q

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28201

A. C. THIES
SENIOR VICE PRESIDENT
PRODUCTION AND TRANSMISSION

P. O. Box 2178

September 5, 1974


Mr. Norman C. Moseley, Director
Directorate of Regulatory Operations
U. S. Atomic Energy Commission
Region II - Suite 818
230 Peachtree Street, Northwest
Atlanta, Georgia 30303

Re: RO:II:NCM
50-269, -270, -287

Dear Mr. Moseley:

In response to your letters of August 5, 1974 and August 16, 1974, which transmitted Directorate of Regulatory Operations Bulletin No. 74-9, we have reviewed the safety systems at Oconee Nuclear Station. There are no General Electric Model 4KV magne-blast circuit breakers utilized in these systems.

Very truly yours,



A. C. Thies

ACT:vr

