

NJK-80-37

February 1, 1980

J. Keppler, Regional Director Office of Inspection and Enforcement Region III U.S. Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, Illinois 60137

Reference:

Quad-Cities Nuclear Power Station Docket No. 50-254, DPR-29, Unit 1 Appendix A, Sections 3.2.G. and 6.6.B.2.c

Enclosed please find Reportable Occurrence Report No. RO 80-01/03L for Quad-Cities Nuclear Power Station.

This report is submitted to you in accordance with the requirements of Technical Specification 6.6.B.2.c, as an observed inadequacy in the implementation of administrative controls which threaten to cause reduction of degree of redundancy provided in an engineered safety feature system.

Very truly yours,

COMMONWEALTH EDISON COMPANY
QUAD-CITIES NCULEAR POWER STATION

N. J. Kalivianakis Station Superintendent

NJK/JCV/san

cc: R. F. Janecek

FEB 7,080 A002 5/1 8002130 040