



**Florida
Power**
CORPORATION

IE FILE COPY

W. P. STEWART, DIRECTOR
POWER PRODUCTION

September 2, 1977

Rec'd

Mr. J. P. O'Reilly, Director
Office of Inspection & Enforcement
U.S. Nuclear Regulatory Commission
230 Peachtree Street, N.W., Suite 818
Atlanta, GA 30303

Dear Mr. O'Reilly:

On June 20, 1977, Florida Power Corporation submitted to the Commission, Licensee Event Report 77-52, which identified an unreviewed safety question as defined by 10 CFR 50.59 (b) concerning untermiated sodium hydroxide dilution of the Reactor Coolant System.

The attached report is being submitted as supplemental information to Licensee Event Report 77-52 and contains the results and conclusions of our review of this safety question.

Upon review and acceptance of this supplemental report by the Commission, appropriate revisions to the CR#3 FSAR will be initiated and submitted at a later date.

Please advise if further discussion is desired.

Very truly yours,

W. P. Stewart

W. P. Stewart

WPC/ECS/mcm5/10
Attachment
File: 3-0-3-a-1

50-302/303

8002 270 630

5

~~1972550049~~