

UNITED STATES ATOM' ENERGY COMMISSION A MEXACINAL SUITE BIB 230 PEAC (REE STREET, NORTHWEST ATLANTA, GEORGIA 30303 DJP "ORATE OF REGULATORY OPERATIONS

NOV 2 0 1972

J. B. Henderson, Chief, Reactor Construction Branch Directorate of Regulatory Operations, Headquarters

FLORIDA POWER CORPORATION (CRYSTAL RIVER 3), LICENSE NO. CPPR-51, DOCKET NO. 50-302

Attached is the report of a special inspection conducted on September 25, 1972, at Crystal River 3.

This inspection was to review the progress made by FPC in removing the defective concrete placement located below the equipment hatch opening. FPC's procedures and repair efforts will be reviewed during future inspections.

C. E. Murphy, Acting Chief Reactor Test and Startup Branch

TELEPHONE: 404: 526-4503

RO:II:CEM

Enclosure: RO Rpt. No. 50-302/72-4

cc w/encl: RO:HQ (5) DR Central Files Regulatory Standards (3) Directorate of Licensing (13)

cc encl. cnly: *PDR *Local PDR *NSIC *DTIE, OR

*To be dispatched at a later date.

8002 270 667

031122