


18 FILE COPY

**Florida
Power**
CORPORATION

18 February 1977
3-0-3-a-1
CS-77-31



Mr. Norman C. Moseley, Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
230 Peachtree St., N.W., Suite 818
Atlanta, Georgia 30303

Docket No. 50-302
License #DPR-72
Licensee Event Report 77-13

Dear Mr. Moseley:

This report is submitted in accordance with Technical Specification 6.9.1 and Regulatory Guide 1.16, Revision 4, Section 4.a. as a written Fourteen (14) Day Report. Mr. R. C. Lewis was notified of this event at 1245 on 11 February 1977.

Cleaning personnel inadvertently actuated deluge system in Reactor Building exhaust filter housing while cleaning the actuation station.

We are in the process of replacing the filters. Corrective action has been taken per the attached Licensee Event Report. There were no safety implications.

Very truly yours,

FLORIDA POWER CORPORATION

W. P. Stewart

W. P. Stewart
Director, Power Production

DWP/feh

Enclosure

YRB

Nuclear Plant Manager

1962

8002 270 686 S