

LICENSEE EVENT REPORT

CONTROL BLOCK: _____
1 5

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME: FLCRP3 LICENSE NUMBER: 00-000000-00 LICENSE TYPE: 41111 EVENT TYPE: 01
7 8 9 14 15 25 26 30 31 32

CATEGORY: CONT REPORT TYPE: * REPORT SOURCE: P DOCKET NUMBER: 050-0302 EVENT DATE: 010177 REPORT DATE: 010377
7 8 57 58 59 60 61 68 69 74 75 80

EVENT DESCRIPTION

02 Discovery of a through wall crack in an eight inch Schedule 40 304 stainless
7 8 9 80
03 steel building spray pipe inside the containment building. Crack is in heat
7 8 9 80
04 affected zone of a pipe-to-pipe weld. The system contains stagnant water.
7 8 9 80
05 _____
7 8 9 80
06 _____ (77-1)
7 8 9 80

SYSTEM CODE: SA CAUSE CODE: E COMPONENT CODE: PIPEXX PRIME COMPONENT SUPPLIER: A COMPONENT MANUFACTURER: K055 VIOLATION: N
7 8 9 10 11 12 17 43 44 47 48

CAUSE DESCRIPTION

08 Suspected stress corrosion cracking due to presence of chlorides and oxygen at a
7 8 9 80
09 location subject to several weld repairs. Investigation is continuing in accord-
7 8 9 80
10 ance with IE Circular 76-06.
7 8 9 80

FACILITY STATUS: B % POWER: 000 OTHER STATUS: Mode 5 METHOD OF DISCOVERY: B DISCOVERY DESCRIPTION: Leakage noted by plant Operator
7 8 9 10 12 13 44 45 46 80

FORM OF ACTIVITY RELEASED: _____ CONTENT OF RELEASE: _____ AMOUNT OF ACTIVITY: NA LOCATION OF RELEASE: _____
7 8 9 10 11 44 45 80

PERSONNEL EXPOSURES

13 NUMBER: _____ TYPE: _____ DESCRIPTION: NA
7 8 9 11 12 13 80

PERSONNEL INJURIES

14 NUMBER: _____ DESCRIPTION: NA
7 8 9 11 12 80

OFFSITE CONSEQUENCES

15 _____ NA
7 8 9 80

LOSS OR DAMAGE TO FACILITY

16 TYPE: _____ DESCRIPTION: NA
7 8 9 10 80

PUBLICITY

17 _____ NA
7 8 9 80

ADDITIONAL FACTORS

18 _____ NA **8002 270710**
7 8 9 80

19 _____
7 8 9 80

NAME: W. P. Stewart PHONE: (813) 866-4159