



**LOUISIANA**  
**POWER & LIGHT**

142 DELARONDE STREET  
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

March 28, 1980

D. L. ASWELL  
Vice President-Power Production

LPL 13398  
Q-3-A35.07.11

Mr. K. V. Seyfrit, Director, Region IV  
U. S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76012

SUBJECT: Waterford SES Unit 3  
Docket No. 50-382  
Final Report of  
Significant Deficiency No. 11  
Switchgear Breaker Position  
Switch Operator Defect

REFERENCE: LP&L Letter LPL 11136 to NRC dated May 10, 1979

Dear Mr. Seyfrit:

In accordance with the requirements of 10 CFR 50.55(e), we are hereby providing two copies of the Final Report of Significant Deficiency No. 11, "Switchgear Breaker Position Switch Operator Defect".

All corrective action work for this significant deficiency is now complete and reinspection has been accomplished. If we can be of further assistance in this matter, please advise.

Yours very truly,

D. L. Aswell  
DLA:TFG:ncd  
Attachment

- cc: 1) Director  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555  
(with 15 copies of report)
- 2) Director  
Office of Management  
Information and Program Control  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555  
(with 1 copy of report)

*Boia 5/11*

8004010343