

NSP

NORTHERN STATES POWER COMPANY

MINNEAPOLIS, MINNESOTA 55401

April 3, 1980

Mr J G Keppler
Office of Inspection & Enforcement
U S Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Dear Mr Keppler:

PRAIRIE ISLAND NUCLEAR GENERATING PLANT
Docket No. 50-282 License No. DPR-42

Update Report-Pipe Hanger and Snubber Deficiencies

A third update Licensee Event Report for occurrence 79-030 has been issued. It is reproduced on the back of this letter. Three copies are provided.

Yours very truly,

David Musolf for

L O Mayer, PE
Manager of Nuclear Support Services

LOM/DMM/ak

cc: Director, IE, USNRC (30)
Director, MIPC, USNRC (3)
MPCA
Attn: J W Ferman

-over-

8 004080 478