

POOR ORIGINAL

DATE: 12/11/80

OFFICE: []

REPORT NUMBER: []

[] T N S N P 1 0 0 - 0 0 0 0 0 - 0 0 4 1 1 1 1

[] L 0 5 0 0 0 3 2 7 0 3 0 7 8 0 0 4 0 3 8 0

[] At the completion of fuel loading but with core alterations still
[] underway, upper internals were installed and RCCA drag testing was
[] performed; SI-65 (which fulfills LCO 3.9.2 and 3.9.5) was not
[] performed. LCO 3.9.2 and 3.9.5 were not fulfilled from the evening
[] shift of 3/5/80 until the day shift of 3/7/80. There was no danger
[] to the health and safety of the public. Previous occurrences - none.

[] z z A A z z z z z z z z
[] 8 0 0 1 6 0 3 L 0
[] H z z z 0 0 0 0 Y N z z 9 9 9

[] Licensed operators were instructed to perform SI-65 during Core
[] Alterations. Previously, they misinterpreted the Tech. Specs. and
[] thought SI-65 was applicable only during fuel movement. This was
[] the first occurrence of this event and no further corrective actions
[] were thought necessary.

[] H 0 0 0 N/A B Operator observation
[] z z N/A N/A
[] 0 0 0 0 N/A
[] 0 0 0 N/A
[] z N/A
[] N N/A

Daniel J. Record

615-842-5208

8004090 336

LER SUPPLEMENTAL INFORMATION

SQRO-50-327/8016 Technical Specifications Involved 3.9.2 and 3.9.5

Reported Under Technical Specification 6.9.1.13.c

Date of Occurrence: 3/5/80 Evening Shift until 3/7/80 Day Shift - Unit 1

Identification and Description of Occurrence:

Operations personnel, in reviewing Technical Specifications, determined the plant had not performed SI-65 (which fulfills 3.9.2 and 3.9.5) during Core Alterations.

Conditions Prior to Occurrence:

Unit 1 in Mode 6 following initial core loading. Upper internals installed and RCCA drag testing in progress.

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

N/A

Apparent Cause of Occurrence:

Misinterpretation of Technical Specification requirements.

Analysis of Occurrence:

There was no hazard to the public health or safety.

Corrective Action:

SI-65, which satisfies Surveillance Requirements 4.9.2.a and 4.9.5, was immediately initiated.

Failure Data:

N/A