



HELPING BUILD ARKANSAS

ARKANSAS POWER & LIGHT COMPANY

P. O. Box 551

Little Rock, Arkansas 72203

February 16, 1977

1-027-9

Reactor Construction and Operations Branch
United States Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region IV
611 Ryan Drive, Suite 1000
Arlington, Texas 76012

Attention: Mr. G. L. Madsen

SUBJECT: ARKANSAS POWER & LIGHT COMPANY
ARKANSAS NUCLEAR ONE - UNIT ONE
DOCKET NO. 50-313, LICENSE NO. DPR-51
IE INSPECTION REPORT NO. 50-313/77-02
FILE: 0232

Gentlemen:

The subject inspection report identified two activities which were in violation of 10CFR50, Appendix B. As applicable, our response includes (1) corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further non-compliance; and (3) the date when full compliance will be achieved. The NRC position on the cited violation and the corresponding AP&L response are provided below:

NRC POSITION

Based on the results of the NRC inspection conducted January 17-21, 1977, it appears that certain of your activities were not conducted in full compliance with your Reactor License or NRC requirements as indicated below:

1. Criterion V of Appendix B to 10CFR50 requires that activities affecting quality shall be prescribed by documented procedures and shall be accomplished in accordance with these procedures. This requirement is further applied by Section 5 of the licensee's NRC approved Quality Assurance Program.

8004110 655

February 14, 1977

Page 2

- a. Contrary to the above, Maintenance Procedure 1405.01 does not include appropriate acceptance criteria for the station battery daily surveillance checks as required by Step 4.1 of Quality Control Procedure 1004.12.
- b. Contrary to the above, the computer printouts for the Power Range Linear Amp Calibration at Power conducted on December 3, 13, 23, 27 and 31, 1976, were not signed as required by Step 7.1 of Surveillance Test Procedure 1304.32.

This is an infraction.

AP&L RESPONSE

1. Maintenance Procedure 1405.01 will be revised to include appropriate acceptance criteria for the station battery daily surveillance checks. This revision is expected to be complete by March 1, 1977.
2. The surveillance test records documenting the execution of Procedure 1304.32 for the month of December, 1976, have been reviewed and endorsed in accordance with the stated requirement. Plant personnel have been instructed to comply with paragraph 7.1 of Procedure 1304.32. It is our belief that, at this time, we are in full compliance with Procedure 1304.32.

Very truly yours,



Donald A. Rueter
Manager, Licensing

DAR:LA:ph