

LICENSEE EVENT REPORT

CONTROL BLOCK: ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

① 01 M N P I N 22 00-000000-000 ③ 41111 ④ ⑤

CON'T
① 01 REPORT SOURCE L6 05000306 ⑦ 031280 ⑧ 041180 ⑨

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES ⑩

02 | With one charging pump out of service, No. 22 charging pump was started but its motor
03 | breaker would not stay closed and the pump stopped. Tech Spec 3.2.B.1 applies. Third
04 | charging pump was operable. Not repetitive. No effect on public health and safety.
05 | In the safety analysis no credit is taken for charging pumps.
06 | _____
07 | _____

① 08 | _____ ⑧ ⑨

① 09 SYSTEM CODE PC ①① CAUSE CODE E ①② CAUSE SUBCODE A ①③ COMPONENT CODE CKITBRK ①④ COMP. SUBCODE A ①⑤ VALVE SUBCODE Z ①⑥

①⑦ LER/RO REPORT NUMBER 80 ②① EVENT YEAR 80 ②② SEQUENTIAL REPORT NO. 011 ②③ OCCURRENCE CODE 03 ②④ REPORT TYPE L ③① REVISION NO. 0 ③②

ACTION TAKEN D ①⑧ FUTURE ACTION Z ①⑨ EFFECT ON PLANT Z ②⑦ SHUTDOWN METHOD Z ③⑥ HOURS 0000 ②② ATTACHMENT SUBMITTED N ③③ NPRD-4 FORM SUB. Y ④② PRIME COMP. SUPPLIER A ④⑤ COMPONENT MANUFACTURER G080 ④⑦

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS ②⑦

10 | Failure of a General Electric Type TFK breaker. Breaker was replaced and No. 22
11 | charging pump was operable in about 5 hours.
12 | _____
13 | _____
14 | _____

① 15 FACILITY STATUS F ②⑧ % POWER 100 ②⑨ OTHER STATUS NA ③⑩ METHOD OF DISCOVERY A ③① DISCOVERY DESCRIPTION Operator observation ③②

① 16 ACTIVITY RELEASED OF RELEASE Z ③③ CONTENT Z ③④ AMOUNT OF ACTIVITY NA ③⑤ LOCATION OF RELEASE NA ③⑥

① 17 PERSONNEL EXPOSURES NUMBER 000 ③⑦ TYPE Z ③⑧ DESCRIPTION NA ③⑨

① 18 PERSONNEL INJURIES NUMBER 000 ④⑦ DESCRIPTION NA ④①

① 19 LOSS OF OR DAMAGE TO FACILITY TYPE Z ④② DESCRIPTION NA ④③

① 20 PUBLICITY ISSUED N ④④ DESCRIPTION NA ④⑤

NAME OF PREPARER A. A. Hunstad PHONE 612-388-4767

8004180 386