

NARRATIVE REPORT

Georgia Power Company
Plant E. I. Hatch
Baxley, Georgia 31513

Reportable Occurrence Report No. 50-366/1980-033.

During the surveillance outage and with the reactor in cold shutdown, the Triaxial Peak Recording Accelerometers on the reactor pedestal and on the feedwater inlet line were not calibrated before 3/30/80 as required by Amendment No. 12 of the Unit II Tech Specs.

Calibrations were started prior to this date (3/20/80) but because of instrument failures the calibrations could not be completed. The instruments were returned to the vendor, Engdahl Enterprises, Costa Mesa, Ca., for repair. They are a model Par 400-1. Unit I does not have this type of instrument.

A special report will be submitted if the instruments are not repaired within 30 days as required by Tech Specs, paragraph 3.3.6.2.