

TENNESSEE VALLEY AUTHORITY
CHATTANOOGA, TENNESSEE 37402

716 Edney Building

April 18, 1980

Mr. James P. O'Reilly, Director
U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 1 - DOCKET
NO. 50-259 - FACILITY OPERATING LICENSE DPR-33 - REPORTABLE OCCURRENCE
REPORT BFR0-50-259/0027

The enclosed report provides details concerning the residual heat
removal service water pump D3 timer which was found to be out of
tolerance while performing Surveillance Instruction 4.2.B-14. This
report is submitted in accordance with Browns Ferry unit 1 Technical
Specification 6.7.2.b(2).

Very truly yours,

TENNESSEE VALLEY AUTHORITY

J. A. Calhoun
Director of Nuclear Power

Enclosure (3)

cc (Enclosure):

Director (3)
Office of Management Information and Program Control
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Director (40)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Mr. Bill Lavalles
Nuclear Safety Analysis Center
Palo Alto, California 94302

Mr. R. F. Sullivan, NRC Inspector, Browns Ferry

A002
S
111

8004220 742