

LICENSEE EVENT REPORT

8004298 407

CONTROL BLOCK: _____ (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	1	L	Q	A	D	2	2	0	0	0	-	0	0	0	-	0	0	0	3	4	1	1	1	1	4	5
7	8	9	LICENSEE CODE					14	15	LICENSE NUMBER								25	26	LICENSE TYPE					30	37	58

0	1	L	6	0	5	0	0	0	2	6	5	7	0	3	2	2	8	0	8	0	4	2	1	8	0	9
7	8	CON'T		REPORT SOURCE		60	61	DOCKET NUMBER				68	69	EVENT DATE				74	75	REPORT DATE				80		

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 While performing the PCI Simulated Automatic Closure Initiation Test, procedure

0 3 QOS 1600-13, TIP machine number 2 failed to automatically withdraw the TIP when a

0 4 Group II isolation signal was initiated. Consequently, the PCI ball valve did not

0 5 close (TS 3.7.D.2). The consequences of this occurrence were minimal since the TIP

0 6 machine could have been manually switched into reverse. The TIP would have then

0 7 withdrawn and the ball valve would have automatically closed. The TIP tube shear

0 8 valve was also available.

0	9	S	D	11	E	12	A	13	R	E	L	A	Y	X	14	A	15	Z	16
7	8	SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE					COMP. SUBCODE		VALVE SUBCODE				
17	18	8	0	—	0	0	9	—	0	3	L	—	0						
LER/RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.									
A	Z	Z	Z	0	0	0	0	N	Y	N	P	2	9	7					
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47					

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The cause of this failure was dirty contacts on TIP machine relay K21. This relay is

1 1 held normally energized by the 120 VAC Group II PCI bus. When an isolation signal

1 2 occurs, the relay de-energizes closing a set of contacts which will withdraw the TIP

1 3 from core. Relay K21 was replaced and the PCI simulated automatic closure initiation

1 4 test was successfully completed.

1	5	H	28	0	0	0	29	NA	30	B	31	Routine Test	32	
7	8	FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY					DISCOVERY DESCRIPTION	

1	6	Z	33	Z	34	NA	35	NA	36	
7	8	ACTIVITY CONTENT		RELEASED OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE		

1	7	0	0	0	37	Z	38	NA	39
7	8	PERSONNEL EXPOSURES		NUMBER		TYPE		DESCRIPTION	

1	8	0	0	0	40	NA	41
7	8	PERSONNEL INJURIES		NUMBER		DESCRIPTION	

1	9	Z	42	NA	43		
7	8	LOSS OF OR DAMAGE TO FACILITY		TYPE		DESCRIPTION	

2	0	N	44	NA	45				
7	8	PUBLICITY ISSUED		DESCRIPTION		NRC USE ONLY			